

# Oil Field Environmental Incident Summary

**Incident:** 20140809134905      **Date/Time of Notice:** 08/09/2014 13:49

**Responsible Party:** STATOIL OIL & GAS LP

**Well Operator:** STATOIL OIL & GAS LP

**Well Name:** PATENT GATE 7-6 #1H

**Field Name:** SAKAKAWEA

**Well File #:** 21244

**Date Incident:** 8/8/2014

**Time Incident:** 20:00

**Facility ID Number:**

**County:** MCKENZIE

**Twp:** 151

**Rng:** 100

**Sec:** 7

**Qtr:**

**Location Description:**

**Submitted By:** Jake Way

**Received By:**

**Contact Person:** Jake Way  
6300 BRIDGE POINT PKY, BLDG 2  
SUITE 500  
AUSTIN, TX 78730

**General Land Use:** Well/Facility Site

**Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:** 1 Mile

**Distance Nearest Water Well:** 1 Mile

**Type of Incident:** Treater Leak

**Release Contained in Dike:** Yes - Within Dike

**Reported to NRC:** No

	Spilled	Units	Recovered	Units	Followup	Units
--	---------	-------	-----------	-------	----------	-------

Oil

Brine	2	Barrels	2	Barrels		
-------	---	---------	---	---------	--	--

Other

**Description of Other Released Contaminant:**

**Inspected:**

**Written Report Received:**

**Clean Up Concluded:**

**Risk Evaluation:**

None

**Areal Extent:**

***Potential Environmental Impacts:***

Affected well site soil will be remediated and properly disposed of.

***Action Taken or Planned:***

All open valves will be plugged/capped to prevent future releases.

***Wastes Disposal Location:*** Newalta

***Agencies Involved:***

***Updates***

---

***Date:*** 8/13/2014    ***Status:*** Reviewed - Assigned to Other Agency

***Author:*** Roberts, Kris

***Updated Oil Volume:***

***Updated Salt Water Volume:***

***Updated Other Volume:***

***Updated Other Contaminant***

***Notes:***

Release, due to a treater leak, remained on location within the diking according to the report. NDIC retains oversight.